



### SECTION V - HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE - Conditions to Avoid  Prolonged use may cause skin irritation, blurred vision.	
PRIMARY ROUTES OF ENTRY  4 INHALATION   4 SKIN CONTACT   4 EYE CONTACT   4 OTHER (Specify) _____	
EMERGENCY AND FIRST AID PROCEDURES  Move to well ventilated area, flush skin or eyes thoroughly with water. If swallowed, do not induce vomiting - get medical attention.	

### SECTION VI - REACTIVITY DATA

STABILITY	UNSTABLE		
	STABLE	X	
HAZARDOUS POLYMERIZATION	MAY OCCUR		
	WILL NOT OCCUR	X	

### SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED  Absorb with absorbent clay or earth. Shovel into containers and dispose of according to local law.
WASTE DISPOSAL METHOD  Dispose into regulatory disposal facilities in accordance with local and state laws.

### SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION None, other than adequate ventilation.		
VENTILATION		
	ADEQUATE	
PROTECTIVE GLOVES (Specify type) Avoid Skin Contact-Rubber Gloves	EYE PROTECTION (specify type) Safety Glasses	
OTHER PROTECTIVE EQUIPMENT Clothing as required to avoid skin contact.		

### SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING  Do not store above 120°F
---

#### ADDITIONAL HEALTH DATA COMMENT

The above information is based on the data of which we are aware and is believed to be correct as of the data hereof. Since the information contained herein may be applied under conditions beyond our control and with which we may be unfamiliar and since data made available subsequent to the date hereof may suggest modification of the information, we do not assume any responsibility for the results of its use. This information is furnished upon condition that the person receiving it shall make his own determination of the suitability of the material for his particular purpose.